


7

Original-Trafo


defekt (verzerrt, leise)

(Satz 6-31)
(Schwarzfeld)

	$R [\Omega]$	$Z [\Omega]$ 1kHz bei $R_L = 5\Omega$
1-2	386	2.9k
4-5	0.55	
6-7	43.3	70

Ersatz-Trafo

(Sondyna 5520)

(*) nur für
Imp. Messung(xx) bei Imp. Messg.
abhängig

	$R [\Omega]$	$Z [\Omega]$ 1kHz bei $R_L = 5\Omega$
1-2	258	8.9k
2-3	3.4	5.2
1-3	262	9.1k
4-5	0.36	
6-7	25.3	91

10.6.24/NS

ELCO